RECEIVING INSPECTION REPORT

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11201

RECEIVED FROM [illegible] #9

DATE REC'D. [illegible]-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322		157	0	10					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
100	737613 Spring Shipper #35920	100	✓	

RECEIVED BY

INSPECTED BY SWQ DATE 2/7/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11218

RECEIVED FROM Laurent Industrial Screw Corp.

DATE REC'D. 1-9-57

P.O. NO. 64428

VENDOR PACKING SLIP NO. 0572

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
		NONE	NONE							

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
1000	730185-146 Pin Taper, #4/0 x ½ lg Stl cad pl AN385-4C-24 322-000000-18280-0-0-00-00-02	1000	✓	

RECEIVED BY